

Oil Field Environmental Incident Summary

Incident: 20160307091707 **Date/Time of Notice:** 03/07/2016 09:17

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-D CVANCARA S-154-93-0904H-2

Field Name: ROBINSON LAKE

Well File #: 23954

Date Incident: 3/6/2016

Time Incident: 15:30

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 93

Sec: 9

Qtr:

Location Description:

Submitted By: Alberto Yates

Received By:

Contact Person: Troy Brunsell
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 4.2 Mile

Distance Nearest Water Well: 4.2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels			2	barrels
Brine					0	barrels
Other					0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/4/2016

Clean Up Concluded: 3/27/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time.

Action Taken or Planned:

A vacuum truck was dispatched to the location to remove the standing fluid. The remaining impacts will be cleaned up and the affected material disposed at an approved waste facility.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 3/7/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the treater building was on fire and burned the insulation. The release was contained to the facility site according to the report. NDIC retains oversight.